

BMW Group - AIR: 2025-01-06 / 23:52
Retailer: 32711/06
Model: 540I XDR A
Vehicle identification number: WBA[REDACTED]
Development code: G31
Model code: JM21
Lead type: JM21

Vehicle

BMW 540I XDR A, 250KW
WBA[REDACTED]



Development code G31
Colour alpinweiss 3
Actual integration level S15A-18-03-520
Start of warranty 26 April 2018

Technical campaigns

There are no Campaigns for this vehicle.

Special information

There are no Campaigns for this vehicle.

Live Diagnosis

ⓘ There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2018-1 (As of: 5 Dec 2022)	-	-	-
Road Map EUROPE EVO 2018-1 (As of: 5 Dec 2022)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2024-2	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	540i XDR A
Body	TOUR
Vehicle identification number (last 7 digits)	B209515
Vehicle identification number (17 digits)	WBA [REDACTED]
Development code	G31
Steering	LL
Engine	B58M
Engine number	[REDACTED]
Exhaust re-treatment	EURO6, ZD, PI/CI, M, N1 I
Transmission	AUT
Transmission number	[REDACTED]
Head unit serial number	HB [REDACTED]
Drive	ALLR
Integration level, works	S15A-18-03-520
Production date	22 Mar 2018
Production plant	Dingolfing
Delivery date	25 Apr 2018
Delivering retailer	BMW AG, C1-V-30, München, DE
National-market version	EUR
Paint code	300
Upholstery code	LCFK
Model code	JM21
Basic type	JM11
Lead type	JM21

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
01CB CO2 equipment
021P BMW LA wheel M double spoke 664
0230 Extra package, EU-speciifc
0248 Steering wheel heater
0258 Tyres with runflat properties
02NH M Sport brake
02PA Locking wheel bolt
02TB Sport automatic gearbox
02VB Tyre pressure display
02VH Integral active front steering
0302 Alarm system

Retrofitted optional equipment:

This vehicle has no retrofits.

0322 Comfort access
0337 M Sports package
03MC M Roof rails high-gloss Shadowline
0402 Panorama glass roof
0420 Sun protection glazing
0423 Floor mats velours
0428 Warning triangle and first aid kit
0441 Smoker package
0481 Sports seat
04HA Seat heating, front and rear
04K7 Interior trim alu.rhomb.w.accent strip
04NB Autom. climate control with 4-zone ctrl
04NE Blow-by heater
04T8 Expanded exterior mirror package
04UR Ambient interior light
0548 Kilometre speedo
0552 Adaptive LED headlight
05A1 LED Fog lights
05AC High-beam assistant
05AL Active Protection
05AT Driving Assistant Plus
05DM Parking assistance system
0609 Navigation system Professional
0610 Head-up display
0650 CD drive
0654 DAB tuner
0676 HiFi speaker system
06AC Intelligent emergency call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NW Telephony with wireless charging
06WD WLAN Hotspot
0704 M Sports suspension
0710 M leather steering wheel
0715 M Aerodynamics package
0760 High gloss shadow line
0775 Headlining anthracite
07R7 Innovation package
07XP Navigation package Connected Drive
0801 National version Germany
0851 Language version German
0879 On-board literature, German
08KA Oil service interval 24 mths / 30,000 km
08R9 Refrigerant R1234yf
08TF Active pedestrian protection
09BD Business Package
A105 105 Ah AGM battery

Control unit software version

Note: Permitted CAL ID/CVN combinations in EURO vehicles.

Control unit	Control unit class	CAL ID	CVN
DME1	DME	0CC7E9F6	0CC7E9F6
DME2	DME	14DB6C0F	14DB6C0F

Vehicle histories

Date	Type	Vehicle mileage	Retailer	Overview
— 05/12/2022	Service	111034 Km	00084 Niederlassung Saarbrücken , Saarbrücken	Automatic

4300	4300	4300	4300
11/2023	11/2023	11/2023	11/2023
✓	✓	✓	✓

	04/2023	04/2023	3600	4300
			✓	✓

03/2023

— 03/12/2022 Key

111034 Km

Key 0

4300	4300	4300	4300
12/2023	12/2023	12/2023	12/2023

	05/2023	05/2023	3600	4300
				12/2023

03/2023

— 03/12/2022 Repair

111047 Km

00084
Niederlassung
Saarbrücken
BMW AG,
Saarbrücken

Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Kunde beanstandet:Kühlmittelverlust. Optisch keine Undichtigkeit,feststellbar.Bitte prüfen und Rücksprache SB. Kulanz wird geprüft.,Fzg. Test durchgeführt zwecks CC-Meldungen,ServiceLösung DE SEL-SEL-P
-11-20000813321275-02 abgearbeitet;- Kühlsystem auf Wasserdichtheit geprüft,=> System hält Druck,=> Hühlmittelpumpe i.O,- Kühlsystem neu entlüftet und Kühlmittelstand im Ausgleichsbehälter,leicht erh
öht,Kühlsystem entlüften und mit Spezialwerk zeug auf Wasserdichtheit prüfen,

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
--	-------

Performing vehicle test Flat rate unit I 00 00 556	3 FRU
---	-------

Bleed the cooling system and check it for watertightness with the special tool Flat rate unit I 17 00 539	6 FRU
--	-------

Anti-freeze Part I 83 19 2 218 348	1
---------------------------------------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words Freigabe 05.12.22 um 11.56 Uhr erhalten.,->SI Paket 46410 Euro buchen.,->Service Bremsen hinten 440 Euro durchführen.,

Service, advisory consultation at vehicle	0 FRU
Flat rate unit I 00 52 050	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Ölzuschlag für Service Inklusive	Local	1
Part I 0000162		

Set oil-filter element	1
Part I 11 42 7 826 799	

BMW Engine Oil LL04 0W30	7
Part I 83 21 2 405 950	

battery	1
Part I 66 12 6 912 985	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölservice - zusätzliche AW	Local	2 FRU
Flat rate unit I IM00 25 0		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 577 170	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Windshield washer antifreeze	1
Part I 83125A1A166	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Set, microfilter/carbon canister	1
----------------------------------	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Spark plug service	5 FRU
Flat rate unit I 00 00 622	

Spark plug, High Power	6
Part I 12 12 0 040 551	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service, vehicle check	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service, rear brakes	8 FRU
Flat rate unit I 00 00 614	

Removing and installing or replacing both rear brake discs	2 FRU
Flat rate unit I 34 21 932	

Repair kit, brake pads asbestos-free	1
Part I 34 21 6 867 175	

Brake-pad paste	1
Part I 83 19 2 158 851	

Brake-pad sensor, rear	1
Part I 34 21 6 890 792	

Safety cleaner 2.0	10
Part I 83 19 2 364 762	

Inner hex bolt	2
Part I 34 21 1 161 806	

Brake disc	2
Part I 34 20 8 853 554	

Torx screw with washer	4
Part I 34 10 8 838 589	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Nachrüstung Service-Inclusive
Part I 5100102

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words Verbundausgleich wechsel Monteur Service kam hinterher!,

Verbundausgleich, wechsel Monteur, Servi
Flat rate unit I AZME000



Local

2 FRU

— 01/12/2021 Key

85680 Km

Key 0





— 01/12/2021 Service

85680 Km

23605
Niederlassung
Saar-Pfalz ,
Kirkel

Automatic



— 01/12/2021 Repair

85680 Km

23605
Niederlassung
Saar-Pfalz
BMW AG,
Kirkel

Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Windshield washer antifreeze
Part I 83125A1A166

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kompaktcheck incl. Flüssigkeiten Sichtpr Flat rate unit I AZ00 11 3	Local	2 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105		2 FRU
--	--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610		3 FRU
--	--	-------

Ölzuschlag für Service Inklusive Part I 0000162	Local	1
--	-------	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950		7
--	--	---

Set oil-filter element Part I 11 42 7 826 799		1
--	--	---

battery Part I 66 12 6 912 985		1
-----------------------------------	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616		2 FRU
---	--	-------

Set, microfilter/carbon canister Part I 64115A1BDB6		1
--	--	---



— Job

Description:

Considered as a repeat visit No

Customer's own words



Fahrzeug NICHT waschen Part I 0012321	Local	1
--	-------	---



— 05/05/2021 Key

70686 Km

Key 0





— 05/05/2021 Service

70686 Km

23605
Niederlassung
Saar-Pfalz ,
Kirkel

Automatic



— 05/05/2021 Repair

70686 Km

23605
Niederlassung
Saar-Pfalz
BMW AG,
Kirkel

Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen derAnnahme
Flat rate unit I 00 52 054

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service
Flat rate unit I 00 00 618

4 FRU

Brake fluid DOT4 LV, low viscosity
Part I 83 13 0 443 030

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche
Part I 0011319

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words Feststellungen:,-Winterreifen hinten 3mm Reifen müssen für den Winter erneuert werden,-FS Plakette fehlt,

Kompaktcheck incl. Flüssigkeiten Sichtpr
Flat rate unit I AZ00 11 3

Local

2 FRU

Windshield washer antifreeze
Part I 83125A1A166



1

— 25/08/2020 Key

55116 Km

23605

Key 1






— 25/08/2020 Service

55116 Km

23605
Niederlassung
Saar-Pfalz ,
Kirkel

Automatic



— 25/08/2020 Repair

55116 Km

23605
Niederlassung
Saar-Pfalz
BMW AG,
Kirkel

Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der
Flat rate unit I 00 52 054

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Spark plug service Flat rate unit I 00 00 622	5 FRU
--	-------

Spark plug, High Power Part I 12 12 0 040 551	6
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

!!! unknown BMW-Id A1BDB6 null !!! Part I A1BDB6	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words Keine einstellarbeiten wegen BSI,-Sitzabdeckung Sitzkonsole Beifahrersitz/Fahrersitz lose.,-CCm wenige Waschwasser.,-Frostschutz unter min.->nach außen keine Undichtigkeit,feststellbar.->ergänzt.Laut SB keine weitere Schadenslokalisierung.,-Felgen vorne rechts/links beschädigt.,-Stoßfänger hinten links beschädigt.,-Gelenkscheibe hinten leicht rissig.Puma-Maßnahme 51849364-04,zutreffend.->Laut Maßnahme liegt die Gelenkscheibe in der Toleranz.,-Luftdruck korrigiert.,-M-Embleme Felgen vorne/hinten rechts fehlt.,

Service, vehicle check Flat rate unit I 00 00 624	6 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	2 FRU
--	-------

Air filter element Part I 13 71 8 577 170	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes Flat rate unit I 00 00 614	8 FRU
--	-------

Repair kit, brake pads asbestos-free Part I 34 21 6 867 175	1
--	---

Brake-pad sensor, rear Part I 34 21 6 890 792	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words Bremsscheiben prüfen ggf ersetzen.,

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Ölzuschlag für Service Inklusive Part I 0000162	Local	1
--	-------	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	7
--	---

Set oil-filter element Part I 11 42 8 583 898	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words -Bremsscheiben vorne unter Sollmindestmaß von 344mm.,->Ist:342mm.,->Bremsscheiben vorne müssen ersetzt werden.,

Removing and installing or replacing both front brake discs Flat rate unit I 34 11 609	8 FRU
---	-------

Brake disc, lightweight, ventilated,left Part I 34 11 6 875 283	1
--	---

Brake disc, lightweight,ventilated,right Part I 34 10 6 875 284	1
--	---

Repair kit, brake pads asbestos-free Part I 34 10 6 888 459	1
--	---

Torx screw with washer Part I 34 10 6 864 424	4
--	---

Inner hex bolt Part I 34 21 1 161 806	4
--	---

Brake pad wear sensor, front Part I 34 35 6 890 788	1
--	---

— 25/08/2020 Repair 55116 Km 23605 Job
Niederlassung
Saar-Pfalz
BMW AG,
Kirkel

— Job

Description:

Considered as a repeat visit No



Customer's own words

Nachrüstung Service-Inclusive Start 5511
Part I 5100102




Local

1

— 05/02/2019 Service 21714 Km 32112 Manual
Autohaus Euler
Kaiserslautern,
Kaiserslautern



— 29/01/2019 Key 21714 Km 32112 Key 0



— 29/01/2019 Repair 21714 Km 32112 Job
Autohaus Euler
Kaiserslautern
GmbH ,
Kaiserslautern Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Free pre-delivery check
Flat rate unit I 00 00 009

15 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Presentation for emission inspection
Flat rate unit I 00 00 527

5 FRU

(Statutory) vehicle inspection
Flat rate unit I 00 12 159

0 FRU

Pre-check for roadworthiness test

5 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test	0 FRU
Flat rate unit I 00 00 004	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Castrol Prof.MP 5 W 30 Longlifeoel	Local	6.5
Part I FT99 99 9 924 8		

Set oil-filter element	1
Part I 11 42 8 583 898	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Set, microfilter/carbon canister	1
Part I 64 11 6 996 208	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Reinigung (Lackier-/Sattlerarbeit)	Local	1 FRU
Flat rate unit I 99 99 999		

TÜV (Lackier-/Sattlerarbeit)	Local	1 FRU
Flat rate unit I 99 99 999		

SRP (Lackier-/Sattlerarbeit)	Local	1 FRU
Flat rate unit I 99 99 999		

Windshield washer antifreeze	2
Part I 83 12 2 409 031	

BMW high-visibility jacket, 2 x	1
Part I 82 26 2 288 693	

20/04/2018	Service	2 Km	31280 ISIS/ ITools int. Kunden Inlan, Dingolfing	Manual
------------	---------	------	---	--------